



**DTB**

Date: December 19, 2005  
Order No.: P-B-27.60/66  
Supersedes:  
Group: 27

**SUBJECT: Model 171.454/456/473, Model Year 2005 – 2006**  
**Model 203.052/054/056, Model Year 2005**  
**Model 209.356/456, Model Year 2006**  
**Model 209.375/475, Model Year 2005 – 2006**  
**Model 211.056/256, Model Year 2006**  
**Model 211.070, Model Year 2004 – 2006**  
**Model 215.375, Model Year 2004 – 2006**  
**Model 219.375, Model Year 2006**  
**Model 220.170/175, Model Year 2004 – 2006**  
**Model 230.475, Model Year 2004 – 2006**  
**Equipped with 7G-Tronic (722.9) Transmission**  
**Flashing with DAS 11/05 and Patch 2005-11-22-0489**

When installing DAS 11/05 on Compact 2 and Compact 3, the SDflash directory was incorrectly loaded onto the hard drive. This may cause older software to be flashed into the control unit.

The installation of the 2005-11-22-0489 patch fixes the SDflash directory and restores normal flashing function. This information was not contained on the 'Pink Note' that was enclosed with the 2005-11-22-0489 patch.

Please ensure that the patch (2005-11-22-0489) has been loaded onto DAS 11/05 before you flash any control module. If the patch (2005-11-22-0489) has not been loaded and you must flash a control unit, please ensure that DAS 11/05 DVD is in the DVD Drive and that you select flash from the DVD Media and **not the hard drive.**



**Note:** This action is critical to ensure that the latest SW application is found and properly flashed to the ECU.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.