



DTB

Date: December 30, 2004
Order No.: P-B-30.30/61
Supersedes:
Group: 30

**SUBJECT: All Passenger Models
Cruise Control Inoperative**



For Information Only!

If you receive customer reports in the above model vehicles where the cruise control disengages at highway speeds, but functions at lower speeds (~25 mph), ensure that a difference in tire circumference between the four tires due to un-uniform wear is not the cause. Additionally; ensure that all 4 tires equipped on the vehicle are identical in the following manner; tire manufacture, application (snow, all-season, performance, etc.), speed, and load ratings.



Note: Version/SCN coding should be considered, if the vehicle recently received a ME software flash or control module replacement.

If you receive reports in the above model vehicles of the cruise control disengaging, please ensure that the vehicle's ME control module is properly version/SCN coded.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.