



DTB

Date: December 9, 2004
Order No.: P-B-49.10/09
Supersedes:
Group: 49

**SUBJECT: Model 171.456, up to chassis F042765
Routing of O2 Sensor Harness**

***i* Note: For Information Only!**

It is NOT required to have the O2 sensor harness (see picture item 2) on the left and right side secured in the retaining clip (Figure 1, 1). As of chassis # F042765 the retaining clips (Figure 1, 1) on the left and right side will no longer be installed.




Figure 1

P-B-49.10/09

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.