





DTB Date: September 9, 2004

Order No.: P-B-83.00/73

Supersedes:

Group: 83

SUBJECT: Model 171.456

Duo Pulsed Valve Leaking Coolant

If you receive customer reports in the above model vehicle that the multifunciton display is indicating low coolant, this may be due to a leak at the hose connections to the duo pulsed valve. Check that the hose connections on the duo pulsed valve are properly seated and correct if necessary. It is not necessary to replace any parts.

Note: The following allowable labor operations should be used when submitting a warranty claim for this repair.

In Case of Warranty

Operation: Engine cooling and heating system pressure test for leaks/deter.condition (includes

tightening connections and adding coolant (20-1010)

Damage Code	Operation Number	Time (hrs.)	Model Indicator (s)
83210 38	20 1010	0.3 hrs.	00

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.