





DTB September 24, 2004

Order No.: P-B-91.40/79

Supersedes:

Group: 91

**SUBJECT:** Model 171.456, up to VIN F018283

**Seat Belt Latch Stop** 

If you receive customer reports in the above model vehicle that the seat belt latch stop on the seat belt is missing on one side, the belt stop can be retrofitted. To resolve, position belt stop, part number indicated below, on seat belt missing the stop and close stop. After installing the stop, it is not possible to remove without damaging.

## **Parts Information**

Qty.	Part Name	Part Number
1	Belt stop	A171 868 00 87 **

\*\*Parts are in a critical supply situation and will be limited, please see the PAC weekly status report on parts availability status and delivery expectations. This report is located on the PAC website.

Note: The following allowable labor operations should be used when submitting a warranty claim for this repair.

## In Case of Warranty

**Operation:** Belt stop – seat belt, install (02-4536)

Damage Code	Operation Number	Time (hrs.)	Model Indicator (s)
91051 ZZ	02 4536	0.1 hrs.	X1

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

www.startekinfo.com