



DTB

Date: December 30, 2004
Order No.: P-B-54.30/127
Supersedes:
Group: 54

**SUBJECT: All 170, 171, 199, 202, 203, 208, 209, 210, 211, 215, 220 and 230
All Model Years with Applicable Warranty Coverage
Instrument Cluster Warranty Claims**

 Note: For Information Only

A number of instrument clusters claimed under warranty have the part number sticker (seal) missing or damaged. Instrument clusters found to have part number sticker (seal) damaged or missing will be returned and the warranty or goodwill claim will be charged back to the dealer as of repair date December 31, 2004. To prevent a part number sticker (seal) from being damaged or removed, please do not open any instrument clusters and do not replace any dial glasses.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.