



DTB

Date: June 21, 2004
Order No.: P-B-58.20/136
Supersedes:
Group: 58

**SUBJECT: Model 171.456
Model 230.474/475/476
Detaching Tool for Washer System Hoses**

Hoses for the washer system in the above model vehicles are now fitted with quick release fittings. If a washer fluid hose or the heat exchanger needs to be replaced or the washer fluid reservoir needs to be removed, special tool, 230 589 13 63 00, is required. Figure 1 demonstrates how the tool is used to disconnect a line.





Figure 1

P-B-58.20/136

Special Tool



230 589 13 63 00

This special tool will automatically be released to all MB dealers in June 2004.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.