



**DTB**

Date: October 13, 2005  
Order No.: P-B-72.18/35a  
Supersedes: P-B-72.18/35 dated October 1, 2004  
Group: 72

**Revision:** *Applicable Models Updated*  
**SUBJECT:** **Model 171.454/456/473**  
**Dirty / Spotted Plastic Interior Trim Parts**

For cleaning the interior trim panels, do not use any dry, rough or hard cloths as the surface of the interior trim panels can be scratched or damaged due to chafing by these incompatible cloths. Our recommendation, for each of the remedies below, would be the use of the Mercedes-Benz microfiber cloth. Parts should not be replaced under warranty. Care in cleaning dirty or spotted plastic interior trim parts (instrument panel, center console, door paneling etc.), is as follows:

Light Contamination: Clean the plastic parts with a moist (use only clean water), fluff-free cloth (e.g. microfiber cloth)

Moderate Contamination: Clean the plastic parts with a moist (use only clean water), fluff-free cloth (e.g. microfiber cloth). A small amount of non-abrasive hand cleanser can also be applied to the cloth.

Severe Contamination: Clean the plastic parts with a moist (use only clean water), fluff-free cloth (e.g. microfiber cloth). Apply a solvent-free and non-corrosive cleaning agent to the cloth, we recommend the Mercedes-Benz cockpit-car care product for this.

 **Warning!**

After cleaning, the surface can briefly assume another shading. In this case wait for the surface to dry.

 **Note:**

No parts should be exchanged with reference to this condition!

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

**Parts Information**

<b>Qty.</b>	<b>Part Name</b>	<b>Part Number</b>
1	Microfiber cloth	A000 986 06 62
1	Cockpit care	A000 986 47 74