

star bulletin



Date: August, 2004
Order No.: P-B-58.40/140

Supersedes:

Group: 58

SUBJECT: Model 171, As of Model Year 2005

Dedicated Straightening Equipment for Collision Repair

A dedicated fixture set from Celette, used for collision repair, is being made available for Model R171 (Figure 1). This set is used in conjunction with MZ towers, Figure 2 on page 2.




Figure 1 P60.10-2124-79

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

REP.	REFERENCE	PDS	NB	MZ
1234567890123456789012345678901234567890123444444444444	7171.7001 7171.7002 7171.7003 7171.7004 7171.7006 7171.7006 7171.7008 7171.7010 7171.7010 7171.7011 7171.7012 7171.7013 7171.7014 7171.7016 7171.7016 7171.7018 7171.7018 7171.7019 7171.7019 7171.7020 7171.7021 7171.7022 7171.7023 7171.7024 7171.7026 7171.7026 7171.7027 7171.7028 7171.7029 7171.7029 7171.7030 7171.7030 7171.7031 7171.7030 7171.7030 7171.7031 7171.7030 7171.7034 7171.7034 7171.7034 7171.7034 7171.7034	44 ₀ 1-1-01-00000-1551-100401441-100300001-003000001 9,9,7,7,6,6,8,8,8,7,7,0,6,6,6,6,6,0,0,0,0,6,6,7,7,0,0,0,1,6,6,6,5,1,6,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0	11211121121161111111221	141 142 260 080 260 060 200 080 200 060 602 601 080 060 200 200 200 140 260 140 140 140 140
()—»	M 6-25 M 8-25 M 10-25 M 12-25 M 12-25 M 12x1,50-30 M 12x1,50-40 M 12x1,50-60		44008040	
9	M 8 M 10 M 12x1,50		10 2 4	

Figure 2 P60.10-2125-73

This set is available via the MBUSA Standard Service Equipment Program (1-888-458-4040).

MZ towers have a wide range of applicability, contact the Standard Service Equipment Program for further information and pricing.

Ordering Information:
See the MBUSA Standard Service Equipment Program Catalog for ordering instructions (1-888-458-4040).

Description	Part Number	Retailer Net (\$)
Base fixture set for model 171 1)	7171.300	\$5,557.50

MZ towers are available separately.